

1982 Mitsubishi Diamond 1A

Serial No. 007 / Registration No. N567JK



Specifications

Year / Manufacturer / Model	1982 Mitsubishi Diamond 1A
Price	\$795,000
Location	Milwaukee, WI
Condition	Used
Serial No. / Reg. No.	0007 / N567JK
Total Time / Landings	6,105 / 5,660

Highlights

- Part 135 Ready
- All Diamond IA Mods
- CVR Replaced w/Overhauled B&D Unit 1/2008
- Autopilot Controller Replaced 1/2008
- New Co-Pilot Windshield 1/2008
- JSSI Engine Coverage
- Price slashed to \$795,000.00

Bringing new technologies to the science of aircraft marketing.

Engines

JSSI Plus Program

#1 ENGINE: 6,105

CSN: 5,700

HSI due in 1104 hours

OVH due in 876 hours

#2 ENGINE: 5,210

CSN: 4,589

HSI due in 1,679 hours

OVH due in 1,655 hours

Avionics

AUTOPILOT: Sperry SPZ-900

CVR: B&D

GLOBAL POSITIONING SYSTEM: King KLN-90B

COMMS: Dual Collins VHF-20A

ENCODING ALTIMETER: Sperry

FLIGHT DIRECTOR SYSTEM: Sperry SPZ-501 IFCS

LONG RANGE NAVIGATION: King KLN-90B

FLIGHT MANAGEMENT SYSTEM: King KLN-90B

NAVS: Dual Collins VIR-30A

ADF: Collins ADF-60A

TRANSPONDER: Dual Collins TDR-90

RADAR: Primus 400WXD

ADC: Allied Signal 242 Color

FLIGHT PHONE: Wulf FF-VI

DME: Dual Collins DME-40

RADAR ALTIMETER: Collins ALT-50

ENHANCED GROUND PROXIMITY WARNING SYSTEM:

Landmark 2000 – TAWS B

Inspection Status

A Inspection Complied with 9/19/08 at 6069.5 hours,
next due 6,269.5 hours

B Inspection Complied with 4/9/07 at 5,868.6 hours,
next due 6,258 hours

C Inspection Complied with 4/15/05 at 5,458 hours, next
due 6,658 hours

D Inspection Complied with 4/15/05 at 5,458 hours,
next due 7, 858 hours

CVR Replaced with Overhauled B&D unit 1/2008

Autopilot controller replaced 1/2008

New co-pilot windshield 1/2008

Additional Equipment

Standby Horizon

Ground Freon Air

Emergency Battery Lights Mod

Increased Takeoff Weight

No Damage History

Turn Radius Mod

6 Brakes

Ice Detection Mod

Aft Baggage Mod

Hot Nozzle Mod

Lear Siegler Starter/Gens

Logo Lights

Lead Acid Battery

Reduced Vertical Separation Minimum Compliant

Interior

The interior of this Diamond IA was completed in March 2005, including a four place club seating, three single seats, forward refreshment center, entertainment center with Airshow 400/DVD/CD with four flat screens, side facing belted flushing lav. Beige Ultra-leather headliner, cream fabric side panels, Bird's Eye Maple cabinetry.

Exterior

Overall white with blue and white stripes. Completed new in 2006.

